














































 <b>80251</b>  <b>M8 x 1.0 Hex Nut</b>	 <b>80253</b>  <b>M10 x 1.25 Hex Nut</b>	 <b>80252</b>  <b>M10 x 1.0 Hex Nut</b>	 <b>80255</b>  <b>M12 x 1.5 Hex Nut</b>	 <b>80254</b>  <b>M12 x 1.25 Hex Nut</b>	 <b>80263</b>  <b>M8 Flat Washer</b>
 <b>80264</b>  <b>M10 Flat Washer</b>	 <b>80265</b>  <b>M12 Flat Washer</b>	 <b>80219</b>  <b>M8 x 1.0 x 20mm</b>	 <b>80221</b>  <b>M8 x 1.0 x 30mm</b>	 <b>80223</b>  <b>M8 x 1.0 x 40mm</b>	 <b>80230</b>  <b>M10 x 1.25 x 20mm</b>
 <b>80232</b>  <b>M10 x 1.25 x 30mm</b>	 <b>80234</b>  <b>M10 x 1.25 x 40mm</b>	 <b>80225</b>  <b>M10 x 1.0 x 20mm</b>	 <b>80227</b>  <b>M10 x 1.0 x 30mm</b>	 <b>80228</b>  <b>M10 x 1.0 x 40mm</b>	 <b>80237</b>  <b>M12 x 1.25 x 25mm</b>
 <b>80238</b>  <b>M12 x 1.25 x 35mm</b>	 <b>80239</b>  <b>M12 x 1.25 x 50mm</b>	 <b>80240</b>  <b>M12 x 1.5 x 20mm</b>	 <b>80241</b>  <b>M12 x 1.5 x 30mm</b>	 <b>80243</b>  <b>M12 x 1.5 x 40mm</b>	 <b>80244</b>  <b>M12 x 1.5 x 50mm</b>