

















































P7290 18-8 Stainless Steel Phillips Pan Head Machine Screws and Hex Nuts PHOTOS ACTUAL SIZE

<p>1  91308</p>  <p>6-32 x 1/2</p>	<p>2  91310</p>  <p>6-32 x 3/4</p>	<p>3  91311</p>  <p>6-32 x 1</p>	<p>4  91312</p>  <p>6-32 x 1-1/4</p>	<p>5  91315</p>  <p>8-32 x 3/8</p>	<p>6  91316</p>  <p>8-32 x 1/2</p>
<p>7  91318</p>  <p>8-32 x 3/4</p>	<p>8  91319</p>  <p>8-32 x 1</p>	<p>9  91334</p>  <p>10-32 x 3/8</p>	<p>10  91335</p>  <p>10-32 x 1/2</p>	<p>11  91337</p>  <p>10-32 x 3/4</p>	<p>12  91338</p>  <p>10-32 x 1</p>
<p>13  91325</p>  <p>10-24 x 3/8</p>	<p>14  91326</p>  <p>10-24 x 1/2</p>	<p>15  91327</p>  <p>10-24 x 3/4</p>	<p>16  91328</p>  <p>10-24 x 1</p>	<p>17  91348</p>  <p>1/4-20 x 1/2</p>	<p>18  91349</p>  <p>1/4-20 x 3/4</p>
<p>19  91350</p>  <p>1/4-20 x 1</p>	<p>20  7060</p>  <p>6-32 Hex Nut</p>	<p>21  7061</p>  <p>8-32 Hex Nut</p>	<p>22  7062</p>  <p>10-32 Hex Nut</p>	<p>23  7063</p>  <p>10-24 Hex Nut</p>	<p>24  91105</p>  <p>1/4-20 Hex Nut</p>