

## PROBLEM SOLVER

### PROBLEM:

**Ordinary taps bind, break, are difficult to start, and require extra torque. This Causes:**

- Extra time spent drilling holes.
- More money to be spent on new taps.

### SOLUTION:

## Regency® Gold Spiral Point Taps

- Binding, dulling, breaking, and seizing are reduced due to superior design and construction.
- Three-flute design starts easier, resulting in straighter tapped holes.
- Short thread design requires less torque.



### APPLICATIONS:

- Machine shops
- Fabrication shops
- Maintenance shops
- Automotive repair shops
- Anywhere threaded holes are needed.



### FEATURES:

- Spiral point design drives chips ahead of the thread — no reversal of the tap needed to clear the chips.
- Three cutting edges cut hard material better.



### FEATURES:

- Agriculture
- Automotive
- Construction
- Education
- Equipment Rental
- Government
- Hospitality
- Manufacturing
- Mining
- Oil & Gas
- Property Management
- Transportation
- Warehousing
- Waste Management